

Premier Property Inspections



Report Especially Prepared For:

Pre Inspection
809 Linden St
Northfield , MN 55057

Inspected By:

Premier Property Inspections
2325 Seurer Ct
Elko New Market, MN 55054
Phone: 612-849-2221
ppi@southmetro-ppi.com
www.southmetro-ppi.com



Date of Inspection: 2/18/2022



Premier Property Inspections

2325 Seurer Ct, Elko New Market, MN 55054

Phone: 612-849-2221

www.southmetro-ppi.com ppi@southmetro-ppi.com

Address of Inspection: 809 Linden St , Northfield , MN 55057

Client: Pre Inspection

Date: 2/18/2022

General Information

Seller's Agent: Jesse Steed
Company: Edina Realty
Phone: ()- -
Email:

Buyer's Agent:
Company:
Phone: ()- -
Email:

Weather Conditions: Sunny 25 ° Fahrenheit
Property Status:

- Occupied
- Vacant
- Partly Occupied
- Utilities Off
- Incomplete

Approximate Square Feet: 1074
Approximate Year Built: 1920

Invoice

Report Number: 20220218-JKF-2
Inspection Type: Visual
Total Fee: \$350.00
Paid By: Check (#Not Paid)

Inspection Agreement:

I the Client, Pre Inspection , have read and agree to all of the following:

The client understands that this Home Inspection is only a visual review of readily accessible areas. The Standards of Practice used meet those prescribed by the American Society of Home Inspectors (A.S.H.I.). No excavation, disassembly or removal of obstructions is performed. Hidden or obstructed defects may not be observed. In addition, some property components are inspected on a random sampling of like items, i.e., electrical outlets, windows, doors, etc. Therefore, not every defect may be identified.

PPI encourages the client to be present at the inspection. This will enable the inspector to point out specific observations, as well as help the client understand any comments provided in the Home Inspection Report. This report is intended for use only by the party contracting for the service. It is not intended to benefit any third party.

The client understands, accepts and agrees that Premier Property Inspections does not impliedly or expressly, warrant or guarantee its Home Inspection, Home Inspection Report, or the condition of the subject property.

In the event that any dispute arises out of, or relates to, the Home Inspection performed or Home Inspection issued under this agreement, such dispute shall be submitted to arbitration for resolution. Election to submit any claim to arbitration must be given, in writing, to Premier Property Inspections within one (1) year of the Home Inspection. The arbitration shall be conducted pursuant to the "Rules and Procedures for the Expedited Arbitration of Home Inspection Disputes" administered by Construction Arbitration Services, Inc. In the event that a dispute is submitted to arbitration pursuant to this paragraph, the decision of the arbitrator shall be final and binding on the parties and judgement on the award of the arbitrator may be entered in any court of competent jurisdiction. As a condition of the reduced fee incorporated herein, our liability shall in no case exceed five times the amount of the fee charged.

Premier Property Inspections expresses no opinion of the subject property beyond what is set forth in its Home Inspection Report. The client may wish to obtain other types of inspections, such as mold, air quality or environmental inspections that are not addressed in the Home Inspection Report. Premier Property Inspections does not inspect for compliance with building codes or regulations of any governmental body, entity or agency.

I, The Client, Pre Inspection acknowledge that by signing this I agree to, and understand all of the terms and conditions stated above and in this report, and waive any claims against The Company, The Company's agents or representatives.

◆Address of Inspection: 809 Linden St , Northfield , MN 55057

no signature captured



◆Client's Signature Date: 2/18/2022

◆Inspector's Signature Date: 2/18/2022

Property Analysis Report

Premier Property Inspections
2325 Seurer Ct, Elko New Market, MN 55054

Date / Time: 2/18/2022 12:00 Weather Conditions: Sunny 25 ° Fahrenheit

Property:

- Occupied Vacant
 Partly Occupied Utilities Off
 Incomplete

Present at inspection:

- Owner Buyer's Agent Buyer Seller's Agent
 Tenant Builder's Representative

Property Type:

- Residential
 Commercial
 Apartment Building

Property Style:

- One Story Two Story
 Three Story Split Foyer / Level
 Contemporary Cape Cod
 Duplex / Multiplex Townhouse / Row
 Condominium Historic
 Modular Chalet
 Tudor / Victorian / Colonial Cottage / Log Cabin

Property Location:

- Inland
 Waterfront
 Top of Hill
 High Wind Area
 Flood Plane
 Earthquake Prone

SUMMARY OF INSPECTION

The inspection resulted in the following summarized items (the locations are listed as viewed from the street facing the property):

Defective Items

- I PLUMBING- Kitchen sink faucet has a slow drip/broken sprayer and the drain inside the base cabinet has a leak at a compression fitting when in use, repairs are needed. (See Figure #35) (See Figure #36)
- I HEATING- The heat duct for the upper east bedroom was not functional at time of inspection. Ducting is suspected to have been altered/removed when the newer larger patio door was installed, evidence of this was found in the basement. (See Figure #42) (See Figure #43)
- I BATHROOM- Handle for the shower lever was broken/damaged, shower can be operated using a pliers to lift valve. (See Figure #47)


Marginal Items

- I GUTTER- Down spout located on the SE corner of home was off/disconnected and laying in the snow. (See Figure #19)
- I TREES- Recommend trimming tree limbs located around the electrical service drop. (See Figure #20)
- I DECK- The deck is rated as marginal due to age of wood, some deterioration and decay was present, no structural deficiencies were observed. (See Figure #21) (See Figure #22)
- I CARBON MONOXIDE- Detectors should be installed within 10 feet of the bedroom doors for safety.
- I SMOKE DETECTORS- All bedrooms lack detector's, recommend installing for safety.
- I ELECTRICAL- Kitchen countertop receptacles should be ground fault protected (G.F.C.I.) for safety.
- I HEATING- The average life expectancy for a furnace is 20-25 years, this unit is 8 years old. Unit is rated as marginal due to a slightly high level of carbon monoxide testing at the exhaust flue located on the rear exterior of home approximately 43 ppm. Recommend a further evaluation by a qualified HVAC technician to ensure safe operation of appliance. (See Figure #37)
- I BASEMENT- Stairwell lacks a hand/guard rail. (See Figure #77)

Exterior

Exterior Doors	<input checked="" type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> See Remarks
Windows and Skylights	<input checked="" type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> See Remarks
Exterior Wall Covering	Location* Front: Vinyl Siding <input checked="" type="checkbox"/> Satisfactory Left: Vinyl Siding <input checked="" type="checkbox"/> Satisfactory Right: Vinyl Siding <input checked="" type="checkbox"/> Satisfactory Rear: Vinyl Siding <input checked="" type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> No Cracks Found <input type="checkbox"/> Common Cracks <input type="checkbox"/> Major Cracks *Location of exterior walls as viewed from the street towards the property
Exterior Trim	<input type="checkbox"/> Wood <input checked="" type="checkbox"/> Metal <input type="checkbox"/> Stucco <input checked="" type="checkbox"/> Satisfactory
Chimney	<input type="checkbox"/> Brick <input type="checkbox"/> Metal <input type="checkbox"/> Block <input type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> N/A Spark Screen: <input type="checkbox"/> Present <input type="checkbox"/> Not Present
Garage and Carport	<input checked="" type="checkbox"/> Garage <input type="checkbox"/> Carport <input checked="" type="checkbox"/> Attached <input type="checkbox"/> Detached <input type="checkbox"/> N/A <input checked="" type="checkbox"/> Satisfactory Door Operator: <input checked="" type="checkbox"/> Operating <input type="checkbox"/> Not Operating <input checked="" type="checkbox"/> Safety Reverse <input type="checkbox"/> N/A
Remarks	<ul style="list-style-type: none"> Typical deteriorative conditions were noted on siding, overall siding is in good condition for age. Light fixture located in the rear of home was missing. (See Figure #1) Some of the windows located on the main floor and garage are older and showing some signs of age via deterioration. (See Figure #2) Basement windows located on the north side of home were insulated with foam board on the exterior of home. (See Figure #3) Walls that are shared with the home and garage should be covered in 5/8 drywall and taped, this is for fire and carbon monoxide protection. (See Figure #4) Image of garage. (See Figure #5) (See Figure #6) (See Figure #7) Image of structure. (See Figure #8) (See Figure #9) (See Figure #10) (See Figure #11)

Figure Number 1



Light fixture located in the rear of home was missing.

Figure Number 2



Some of the windows located on the main floor and garage are older and showing some signs of age via deterioration.

Figure Number 3



Basement windows located on the north side of home were insulated with foam board on the exterior of home.

Figure Number 4



Walls that are shared with the home and garage should be covered in 5/8 drywall and taped, this is for fire and carbon monoxide protection.

Figure Number 5




Image of garage.

Figure Number 6



Image of garage.

Figure Number 7



Image of garage.

Figure Number 8



Image of structure.

Figure Number 9



Image of structure.

Figure Number 10



Image of structure.

Figure Number 11



Image of structure.

Roof

Roof Covering Type	<input type="checkbox"/> Concrete Tile <input type="checkbox"/> Clay Tile <input checked="" type="checkbox"/> Asphalt Composition <input type="checkbox"/> Rolled Asphalt <input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> Wood Shingles <input type="checkbox"/> Built Up <input checked="" type="checkbox"/> Rubber Membrane How Observed: Walked on Roof <input checked="" type="checkbox"/> Unable to fully view entire roof due to unsafe access or possible damage to the roofing
Roof Leaks	<input type="checkbox"/> Some Signs <input type="checkbox"/> Extensive <input checked="" type="checkbox"/> None Observed
Cracked/Broken/Missing Tiles	<input type="checkbox"/> Some Signs <input type="checkbox"/> Extensive <input checked="" type="checkbox"/> None Observed <input type="checkbox"/> N/A
Worn/Missing Shingles	<input type="checkbox"/> Some Signs <input type="checkbox"/> Extensive <input checked="" type="checkbox"/> None Observed <input type="checkbox"/> N/A
Flashing, Soffits and Fascias	<input checked="" type="checkbox"/> Aluminum <input checked="" type="checkbox"/> Galvanized <input type="checkbox"/> Vinyl <input type="checkbox"/> Mineral <input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> N/A
Gutters, Downspouts and Scuppers	<input checked="" type="checkbox"/> Aluminum <input type="checkbox"/> Galvanized <input type="checkbox"/> Vinyl <input type="checkbox"/> Plastic <input checked="" type="checkbox"/> Marginal <input type="checkbox"/> N/A
Remarks	<ul style="list-style-type: none"> Roofing material is approximately 16 years old and was in acceptable condition overall related age. (See Figure #12) Image of roofing. (See Figure #13) (See Figure #14) (See Figure #15) (See Figure #16) Evidence of newer repairs were found on rear of roof via newer shingles. Moreover some of the rubber membrane was loose at corners needing to be re-secured with adhesive. (See Figure #17) (See Figure #18) GUTTER- Down spout located on the SE corner of home was off/disconnected and laying in the snow. (See Figure #19) See Summary Remarks

Figure Number 12



Roofing material is approximately 16 years old and was in acceptable condition overall related age.

Figure Number 13



Image of roofing.

Figure Number 14



Image of roofing.

Figure Number 15



Image of roofing.

Figure Number 16



Image of roofing.

Figure Number 17



Evidence of newer repairs were found on rear of roof via newer shingles. Moreover some of the rubber membrane was loose at corners needing to be re-secured with adhesive.

Figure Number 18



Evidence of newer repairs were found on rear of roof via newer shingles. Moreover some of the rubber membrane was loose at corners needing to be re-secured with adhesive.

Figure Number 19




GUTTER- Down spout located on the SE corner of home was off/disconnected and laying in the snow.

Grounds 1

Grading	General Grading: <input checked="" type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> See Remarks
Sidewalk and Walkway	<input checked="" type="checkbox"/> Concrete <input type="checkbox"/> Brick <input checked="" type="checkbox"/> Common Cracks <input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> N/A
Driveway	<input checked="" type="checkbox"/> Concrete <input type="checkbox"/> Asphalt <input type="checkbox"/> Common Cracks <input checked="" type="checkbox"/> Gravel <input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> N/A
Window Wells	<input checked="" type="checkbox"/> Metal <input type="checkbox"/> Brick <input type="checkbox"/> Concrete <input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> N/A
Retaining Wall (s)	<input type="checkbox"/> Block <input type="checkbox"/> Brick <input type="checkbox"/> Stone <input type="checkbox"/> Concrete <input type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> N/A <input type="checkbox"/> Mortared Joints <input type="checkbox"/> Dry <input type="checkbox"/> Weep Holes
Sprinkler System	<input type="checkbox"/> Operating <input type="checkbox"/> Not Operating <input type="checkbox"/> Random Testing <input type="checkbox"/> Not Tested <input type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> N/A Type: <input type="checkbox"/> Manual <input type="checkbox"/> Automatic Location: <input type="checkbox"/> Front <input type="checkbox"/> Rear
Trees and Shrubs	<input checked="" type="checkbox"/> Monitor tree limbs/vines near roof edge to extend roof life <input checked="" type="checkbox"/> Marginal <input type="checkbox"/> N/A <input type="checkbox"/> Vegetation close to exterior surface blocking full view
Remarks	<ul style="list-style-type: none"> TREES- Recommend trimming tree limbs located around the electrical service drop. (See Figure #20) Heavy snow cover limited inspection of grounds, recommend inspecting landscaping when snow melts to ensure proper drainage around the home. See Summary Remarks

Figure Number 20



TREES- Recommend trimming tree limbs located around the electrical service drop.

Grounds 2


Fencing	<input type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> N/A <input type="checkbox"/> Block <input type="checkbox"/> Wood <input type="checkbox"/> Metal <input type="checkbox"/> Stucco Facing <input type="checkbox"/> Concrete Interlock
Front Porch	<input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> N/A Floor: <input type="checkbox"/> Concrete <input checked="" type="checkbox"/> Wood
Patio #1	<input type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> N/A Floor: <input type="checkbox"/> Concrete <input type="checkbox"/> Wood <input type="checkbox"/> Brick <input type="checkbox"/> Stone Cover: <input type="checkbox"/> Open Design <input type="checkbox"/> Enclosed <input type="checkbox"/> Covered Roof Barbeque: <input type="checkbox"/> Natural Gas <input type="checkbox"/> Propane <input type="checkbox"/> Fired <input type="checkbox"/> Not Fired
Patio #2	<input type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> N/A Floor: <input type="checkbox"/> Concrete <input type="checkbox"/> Wood <input type="checkbox"/> Brick <input type="checkbox"/> Stone Cover: <input type="checkbox"/> Open Design <input type="checkbox"/> Enclosed <input type="checkbox"/> Covered Roof Barbeque: <input type="checkbox"/> Natural Gas <input type="checkbox"/> Propane <input type="checkbox"/> Fired <input type="checkbox"/> Not Fired
Deck / Balcony	<input checked="" type="checkbox"/> Marginal <input type="checkbox"/> N/A Floor: <input checked="" type="checkbox"/> Wood <input type="checkbox"/> Metal <input type="checkbox"/> Concrete Cover: <input checked="" type="checkbox"/> Open Design <input type="checkbox"/> Enclosed <input type="checkbox"/> Covered Roof
Remarks	<ul style="list-style-type: none"> I DECK- The deck is rated as marginal due to age of wood, some deterioration and decay was present, no structural deficiencies were observed. (See Figure #21) (See Figure #22) I See Summary Remarks

Figure Number 21



DECK- The deck is rated as marginal due to age of wood, some deterioration and decay was present, no structural deficiencies were observed.

Figure Number 22



DECK- The deck is rated as marginal due to age of wood, some deterioration and decay was present, no structural deficiencies were observed.

Electrical

Service Entrance Cable	Capacity: 100 amps <input checked="" type="checkbox"/> 120 Volts <input checked="" type="checkbox"/> 240 Volts <input checked="" type="checkbox"/> Satisfactory Service Line Entrance: <input checked="" type="checkbox"/> Overhead <input type="checkbox"/> Underground Conductor Material: <input type="checkbox"/> Aluminum <input type="checkbox"/> Copper <input checked="" type="checkbox"/> Stranded Aluminum <input type="checkbox"/> Not Visible
Service Grounding	<input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> See Remarks
Service Disconnect	Location of the main service disconnect: Electric Panel
Electrical Panel Boxes	Location: Basement <input checked="" type="checkbox"/> Grounded <input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> Fuses <input checked="" type="checkbox"/> Circuit Breakers <input checked="" type="checkbox"/> Subpanel Location: Basement Capacity of main current disconnect: 100 amps
Circuit and Conductors	Wiring: <input checked="" type="checkbox"/> Copper <input type="checkbox"/> Aluminum <input checked="" type="checkbox"/> Stranded Aluminum <input checked="" type="checkbox"/> Satisfactory GFCI: <input type="checkbox"/> Exterior <input type="checkbox"/> Garage <input type="checkbox"/> Kitchen <input checked="" type="checkbox"/> Bathroom(s) <input type="checkbox"/> Basement <input type="checkbox"/> N/A AFCI: <input type="checkbox"/> Operating <input type="checkbox"/> Breaker does not trip when tested <input checked="" type="checkbox"/> N/A
Outlets, Fixtures, and Switches	<input checked="" type="checkbox"/> Random Testing <input type="checkbox"/> Reverse Polarity <input type="checkbox"/> Open Ground <input checked="" type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> Personal belongings prevent testing of all outlets and switches
Smoke Detector	<input checked="" type="checkbox"/> Operating <input type="checkbox"/> Not Operating <input type="checkbox"/> Inaccessible <input checked="" type="checkbox"/> See Remarks
Carbon Monoxide Detector	<input checked="" type="checkbox"/> Operating <input type="checkbox"/> Not Operating <input type="checkbox"/> Inaccessible <input checked="" type="checkbox"/> See Remarks
Remarks	<ul style="list-style-type: none"> I Testing of the circuit breakers and load calculations is outside the scope of this inspection. (See Figure #23) I Low voltage wiring I.E. cable, phone, I.T. systems are outside the scope of this inspection. (See Figure #24) I Image of service meter. (See Figure #25) I Image of panel. (See Figure #26) I ELECTRICAL- Kitchen countertop receptacles should be ground fault protected (G.F.C.I.) for safety. I SMOKE DETECTORS- All bedrooms lack detector's, recommend installing for safety. I CARBON MONOXIDE- Detectors should be installed within 10 feet of the bedroom doors for safety. I Image of the sub-panel. (See Figure #27) I See Summary Remarks

Figure Number 23



Testing of the circuit breakers and load calculations is outside the scope of this inspection.

Figure Number 24



Low voltage wiring I.E. cable, phone, I.T. systems are outside the scope of this inspection.

Figure Number 25



Image of service meter.

Figure Number 26




Image of panel.

Figure Number 27



Image of the sub-panel.

Plumbing

Water Service	<input checked="" type="checkbox"/> Public <input type="checkbox"/> Private <input checked="" type="checkbox"/> Satisfactory
Entrance Pipe	<input checked="" type="checkbox"/> Copper <input type="checkbox"/> Galvanized <input type="checkbox"/> Brass <input type="checkbox"/> Plastic <input type="checkbox"/> PVC <input type="checkbox"/> Unknown
Shut Off Devices	The location of main water supply shutoff device: Water Meter The location of main gas supply shutoff device: Left Exterior Wall
Pipes	<input checked="" type="checkbox"/> Copper <input checked="" type="checkbox"/> Galvanized <input type="checkbox"/> Plastic <input type="checkbox"/> Polybutylene <input checked="" type="checkbox"/> Satisfactory Water Pressure: 65 psi <input checked="" type="checkbox"/> Tested at Interior <input type="checkbox"/> Tested at Exterior <input checked="" type="checkbox"/> Satisfactory Leaks: <input checked="" type="checkbox"/> Leaks Observed <input type="checkbox"/> None Observed Hosebibs: <input type="checkbox"/> Operating <input type="checkbox"/> Not Operating <input checked="" type="checkbox"/> Not Tested
Drain / Waste / Vent Pipes	<input checked="" type="checkbox"/> Plastic <input type="checkbox"/> Copper <input checked="" type="checkbox"/> Galvanized <input type="checkbox"/> Lead <input checked="" type="checkbox"/> Cast Iron <input type="checkbox"/> Slow Drain <input checked="" type="checkbox"/> Leaks <input type="checkbox"/> None Observed Waste Disposal: <input checked="" type="checkbox"/> Public <input type="checkbox"/> Private Septic System
Fuel Distribution	<input checked="" type="checkbox"/> Copper <input type="checkbox"/> Brass <input checked="" type="checkbox"/> Black Iron <input type="checkbox"/> Stainless Steel <input type="checkbox"/> CSST <input type="checkbox"/> Not visible Main Fuel Shut-off Location: Basement
Sump Pumps	<input type="checkbox"/> Satisfactory <input type="checkbox"/> See Remarks <input checked="" type="checkbox"/> N/A
Water Heater	Location: Basement Capacity: 40 gallon <input checked="" type="checkbox"/> Satisfactory Make: Kenmore Age: 8 years S/N: 1438A001013 <input type="checkbox"/> N/A <input checked="" type="checkbox"/> Gas <input type="checkbox"/> Electric <input checked="" type="checkbox"/> Relief Valve <input checked="" type="checkbox"/> Extension
Recirculation Pump	<input type="checkbox"/> Operating <input type="checkbox"/> Not Operating <input type="checkbox"/> Not Tested <input checked="" type="checkbox"/> N/A
Water Conditioning	<input checked="" type="checkbox"/> Water conditioning equipment was present. We cannot determine the effectiveness or proper operability of this equipment within the time and testing parameters of this inspection. <input type="checkbox"/> N/A <input checked="" type="checkbox"/> Did Not Inspect
Laundry Plumbing	Type of energy supply for Dryer: <input type="checkbox"/> Gas <input type="checkbox"/> Electric (110V) <input checked="" type="checkbox"/> Electric (220V) <input type="checkbox"/> Did Not Inspect
Remarks	<ul style="list-style-type: none"> Water softeners are outside the scope of this inspection. (See Figure #28) The average life expectancy for the hot water heater is 10-15 years, this unit is 8 year(s) old. (See Figure #29) Image of water heater burner. (See Figure #30) Image of main gas shut off in basement. (See Figure #31) Image of gas meter. (See Figure #32) Image of water meter and main shut off. (See Figure #33) Image of the washer and dryer, a cycle was ran through the units however its difficult to determine the effectiveness of appliances. (See Figure #34) PLUMBING- Kitchen sink faucet has a slow drip/broken sprayer and the drain inside the base cabinet has a leak at a compression fitting when in use, repairs are needed. (See Figure #35) (See Figure #36) See Summary Remarks

Figure Number 28



Water softeners are outside the scope of this inspection.

Figure Number 29



The average life expectancy for the hot water heater is 10-15 years, this unit is 8 year(s) old.

Figure Number 30



Image of water heater burner.

Figure Number 31



Image of main gas shut off in basement.

Figure Number 32



Image of gas meter.

Figure Number 33



Image of water meter and main shut off.

Figure Number 34



Image of the washer and dryer, a cycle was ran through the units however its difficult to determine the effectiveness of appliances.

Figure Number 35



PLUMBING- Kitchen sink faucet has a slow drip/broken sprayer and the drain inside the base cabinet has a leak at a compression fitting when in use, repairs are needed.

Figure Number 36



PLUMBING- Kitchen sink faucet has a slow drip/broken sprayer and the drain inside the base cabinet has a leak at a compression fitting when in use, repairs are needed.

Heating

Heating System	<input checked="" type="checkbox"/> Marginal <input type="checkbox"/> N/A <input checked="" type="checkbox"/> Forced Air Furnace <input type="checkbox"/> Heat Pump <input type="checkbox"/> Baseboard
Heating Unit #1	Capacity: 60000 BTU Make: International Comfort S/N: A141149988 When turned on by thermostat: <input checked="" type="checkbox"/> Fired <input type="checkbox"/> Did Not Fire
Fuel Supply	<input checked="" type="checkbox"/> Gas <input type="checkbox"/> Electric <input type="checkbox"/> Propane
Heat Exchanger	<input type="checkbox"/> Partially Observed <input checked="" type="checkbox"/> Not Visible; Enclosed Combustion <input type="checkbox"/> N/A
Distribution	<input checked="" type="checkbox"/> Ductwork <input type="checkbox"/> Radiator Heat source in each room: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Filter	<input type="checkbox"/> Washable <input checked="" type="checkbox"/> Disposable <input type="checkbox"/> Electronic <input type="checkbox"/> Electrostatic <input type="checkbox"/> N/A
Fireplace	<input type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> N/A <input type="checkbox"/> Wood Burning <input type="checkbox"/> Gas <input type="checkbox"/> Enclosed Gas Appliances <input type="checkbox"/> Free-Standing <input type="checkbox"/> Flue Liner Damper: <input type="checkbox"/> Operating <input type="checkbox"/> Not Operating <input type="checkbox"/> Recommend a damper stop on fireplace damper for safety Location: n/a Location: n/a Location: n/a Location: n/a
Remarks	<ul style="list-style-type: none"> HEATING- The average life expectancy for a furnace is 20-25 years, this unit is 8 years old. Unit is rated as marginal due to a slightly high level of carbon monoxide testing at the exhaust flue located on the rear exterior of home approximately 43 ppm. Recommend a further evaluation by a qualified HVAC technician to ensure safe operation of appliance. (See Figure #37) A carbon monoxide test was performed at random registers throughout the home and zero PPM (parts per million) was detected. It should be noted that cracks and broken welds in the heat exchanger may not always be detected. (See Figure #38) Image of furnace burners. (See Figure #39) Annual cleaning and inspection is recommended for optimum efficiency. (See Figure #40) PPI recommends that filters should be checked monthly and replaced as necessary. (See Figure #41) HEATING- The heat duct for the upper east bedroom was not functional at time of inspection. Ducting is suspected to have been altered/removed when the newer larger patio door was installed, evidence of this was found in the basement. (See Figure #42) (See Figure #43) It should be noted that thin insulation around ductwork in basement likely contains asbestos, do not disturb this material without testing. (See Figure #44) See Summary Remarks

Figure Number 37



HEATING- The average life expectancy for a furnace is 20-25 years, this unit is 8 years old. Unit is rated as marginal due to a slightly high level of carbon monoxide testing at the exhaust flue located on the rear exterior of home approximately 43 ppm. Recommend a further evaluation by a qualified HVAC technician to ensure safe operation of appliance.

Figure Number 38



A carbon monoxide test was performed at random registers throughout the home and zero PPM (parts per million) was detected. It should be noted that cracks and broken welds in the heat exchanger may not always be detected.

Figure Number 39



Image of furnace burners.

Figure Number 40



Annual cleaning and inspection is recommended for optimum efficiency.

Figure Number 41



PPI recommends that filters should be checked monthly and replaced as necessary.

Figure Number 42




HEATING- The heat duct for the upper east bedroom was not functional at time of inspection. Ducting is suspected to have been altered/removed when the newer larger patio door was installed, evidence of this was found in the basement.

Figure Number 43



HEATING- The heat duct for the upper east bedroom was not functional at time of inspection. Ducting is suspected to have been altered/removed when the newer larger patio door was installed, evidence of this was found in the basement.

Figure Number 44



It should be noted that thin insulation around ductwork in basement likely contains asbestos, do not disturb this material without testing.

Cooling

Cooling System	<input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> N/A <input checked="" type="checkbox"/> Central Air <input type="checkbox"/> Room Units <input type="checkbox"/> Heatpump <input checked="" type="checkbox"/> Evaporate Cooler <input checked="" type="checkbox"/> Electric Compressor <input checked="" type="checkbox"/> Ductwork
Cooling Unit #1	Capacity: Make: Lennox S/N: 5806H27907 <input type="checkbox"/> Tested <input checked="" type="checkbox"/> Not Tested Temperature Differential: No 1: Not Tested No 2: (Temperature differential measured from register to return)
Remarks	1 The average life expectancy for the air conditioning system and its components is 20-25 years, this unit is approximately 16 year(s) old. Industry standards indicate if the ambient temperature is below 65 degrees the a/c system can not be tested. This is due to the viscosity of the oil in the compressor may cause damage to the unit, a visual inspection was performed. (See Figure #45)

Figure Number 45



The average life expectancy for the air conditioning system and its components is 20-25 years, this unit is approximately 16 year(s) old. Industry standards indicate if the ambient temperature is below 65 degrees the a/c system can not be tested. This is due to the viscosity of the oil in the compressor may cause damage to the unit, a visual inspection was performed.

Master Bathroom

<input type="checkbox"/> Built in Tub	<input checked="" type="checkbox"/> Tub/Shower	<input type="checkbox"/> Stall Shower	<input type="checkbox"/> Spa Tub	<input type="checkbox"/> Urinal
<input checked="" type="checkbox"/> Toilet	<input checked="" type="checkbox"/> Sink	<input checked="" type="checkbox"/> Vanity	<input checked="" type="checkbox"/> Window	<input checked="" type="checkbox"/> Fan
Shower Wall Covering: Tile		<input type="checkbox"/> Steam Unit	<input type="checkbox"/> Bidet	
Floor: Tile		<input type="checkbox"/> Spa Tub/Shower		
<input type="checkbox"/> Separations noted in grout in the bathroom tub/shower. Recommend maintenance to ensure water tightness.				
Leaks: <input type="checkbox"/> Some Signs <input checked="" type="checkbox"/> None Observed				

Remarks

- I Image of room. (See Figure #46)
- I BATHROOM- Handle for the shower lever was broken/damaged, shower can be operated using a pliers to lift valve. (See Figure #47)
- I See Summary Remarks

Figure Number 46




Image of room.

Figure Number 47



BATHROOM- Handle for the shower lever was broken/damaged, shower can be operated using a pliers to lift valve.

Kitchen

Cabinets and Countertops	<input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> See Remarks
Sink	Plumbing Leaks: <input checked="" type="checkbox"/> Some Signs <input type="checkbox"/> None Observed <input checked="" type="checkbox"/> Defective
Dishwasher	<input checked="" type="checkbox"/> Operating <input type="checkbox"/> Not Operating <input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> N/A <input checked="" type="checkbox"/> Airgap Device <input type="checkbox"/> Airgap Device Not Visible <input type="checkbox"/> No Airgap Method Provided <input type="checkbox"/> Rusted racks noted inside dishwasher
Range/Oven	<input checked="" type="checkbox"/> Operating <input type="checkbox"/> Not Operating <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Electric <input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> N/A
Exhaust/Recirculating Fan	<input checked="" type="checkbox"/> Operating <input type="checkbox"/> Not Operating <input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> N/A
Other Appliances	Disposal: <input type="checkbox"/> Operating <input type="checkbox"/> Not Operating <input type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> N/A Microwave: <input checked="" type="checkbox"/> Operating <input type="checkbox"/> Not Operating <input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> N/A Compactor: <input type="checkbox"/> Operating <input type="checkbox"/> Not Operating <input type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> N/A Reverse Osmosis: <input checked="" type="checkbox"/> Operating <input type="checkbox"/> Not Operating <input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> N/A Instant Hot Water: <input type="checkbox"/> Operating <input type="checkbox"/> Not Operating <input type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> N/A
Floor	<input type="checkbox"/> Sheetgoods <input checked="" type="checkbox"/> Tile <input type="checkbox"/> Wood <input checked="" type="checkbox"/> Satisfactory
Remarks	<ul style="list-style-type: none"> I Image of kitchen appliances. (See Figure #48) (See Figure #49) (See Figure #50) (See Figure #51) I Image of kitchen. (See Figure #52) (See Figure #53) I See electrical section for details.

Figure Number 48



Image of kitchen appliances.

Figure Number 49



Image of kitchen appliances.

Figure Number 50



Image of kitchen appliances.

Figure Number 51



Image of kitchen appliances.

Figure Number 52




Image of kitchen.

Figure Number 53



Image of kitchen.

Master Bedroom

Floor Coverings	<input type="checkbox"/> Tile <input type="checkbox"/> Sheetgoods <input type="checkbox"/> Wood <input checked="" type="checkbox"/> Wall to Wall Carpet <input checked="" type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> Not Fully Visible
Walls	<input type="checkbox"/> Plaster <input checked="" type="checkbox"/> Drywall <input type="checkbox"/> Masonry <input type="checkbox"/> Common Cracks <input checked="" type="checkbox"/> Satisfactory
Ceilings	<input type="checkbox"/> Plaster <input checked="" type="checkbox"/> Drywall <input type="checkbox"/> Wood <input type="checkbox"/> Acoustical Tile <input type="checkbox"/> Common Cracks <input checked="" type="checkbox"/> Satisfactory
Interior Doors	<input checked="" type="checkbox"/> Hollow Core <input type="checkbox"/> Raised Panel <input type="checkbox"/> Solid Core <input type="checkbox"/> ByPass <input type="checkbox"/> BiFold <input type="checkbox"/> Pocket <input type="checkbox"/> See Remarks
Windows	<input type="checkbox"/> Sliding <input type="checkbox"/> Single Hung <input checked="" type="checkbox"/> Double Hung <input type="checkbox"/> Single Pane <input checked="" type="checkbox"/> Dual Paned <input type="checkbox"/> Fixed <input type="checkbox"/> Casement <input type="checkbox"/> Metal <input checked="" type="checkbox"/> Wood <input type="checkbox"/> Vinyl Security Bars: <input type="checkbox"/> Present <input checked="" type="checkbox"/> Not Present <input type="checkbox"/> Safety Releases <input type="checkbox"/> Become familiar with operation of safety releases on security bars
Remarks	I Image of room. (See Figure #54) (See Figure #55) (See Figure #56)

Figure Number 54



Image of room.

Figure Number 55



Image of room.

Figure Number 56



Image of room.

Bedroom #2 E

Floor Coverings	<input type="checkbox"/> Tile <input type="checkbox"/> Sheetgoods <input type="checkbox"/> Wood <input type="checkbox"/> Wall to Wall Carpet <input checked="" type="checkbox"/> Wood Laminate <input checked="" type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> Not Fully Visible
Walls	<input type="checkbox"/> Plaster <input checked="" type="checkbox"/> Drywall <input type="checkbox"/> Masonry <input type="checkbox"/> Common Cracks <input checked="" type="checkbox"/> Satisfactory
Ceilings	<input type="checkbox"/> Plaster <input checked="" type="checkbox"/> Drywall <input type="checkbox"/> Wood <input type="checkbox"/> Acoustical Tile <input type="checkbox"/> Common Cracks <input checked="" type="checkbox"/> Satisfactory
Interior Doors	<input type="checkbox"/> Hollow Core <input checked="" type="checkbox"/> Raised Panel <input checked="" type="checkbox"/> Solid Core <input type="checkbox"/> Bypass <input type="checkbox"/> BiFold <input type="checkbox"/> Pocket <input type="checkbox"/> See Remarks
Windows	<input type="checkbox"/> Sliding <input type="checkbox"/> Single Hung <input checked="" type="checkbox"/> Double Hung <input type="checkbox"/> Single Pane <input checked="" type="checkbox"/> Dual Paned <input type="checkbox"/> Fixed <input type="checkbox"/> Casement <input type="checkbox"/> Metal <input checked="" type="checkbox"/> Wood <input type="checkbox"/> Vinyl Security Bars: <input type="checkbox"/> Present <input checked="" type="checkbox"/> Not Present <input type="checkbox"/> Safety Releases <input type="checkbox"/> Become familiar with operation of safety releases on security bars
Remarks	<ul style="list-style-type: none"> Image of room. (See Figure #57) (See Figure #58) (See Figure #59) Rear window did not clasp shut when operated. (See Figure #60) See heating section for room details.

Figure Number 57




Image of room.

Figure Number 58



Image of room.

Figure Number 59




Image of room.

Figure Number 60



Rear window did not clasp shut when operated.

Bedroom #3 NW

Floor Coverings	<input type="checkbox"/> Tile <input type="checkbox"/> Sheetgoods <input type="checkbox"/> Wood <input type="checkbox"/> Wall to Wall Carpet <input checked="" type="checkbox"/> Wood Laminate <input checked="" type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> Not Fully Visible
Walls	<input type="checkbox"/> Plaster <input checked="" type="checkbox"/> Drywall <input type="checkbox"/> Masonry <input type="checkbox"/> Common Cracks <input checked="" type="checkbox"/> Satisfactory
Ceilings	<input type="checkbox"/> Plaster <input checked="" type="checkbox"/> Drywall <input type="checkbox"/> Wood <input type="checkbox"/> Acoustical Tile <input type="checkbox"/> Common Cracks <input checked="" type="checkbox"/> Satisfactory
Interior Doors	<input type="checkbox"/> Hollow Core <input checked="" type="checkbox"/> Raised Panel <input checked="" type="checkbox"/> Solid Core <input type="checkbox"/> Bypass <input type="checkbox"/> BiFold <input type="checkbox"/> Pocket <input type="checkbox"/> See Remarks
Windows	<input type="checkbox"/> Sliding <input type="checkbox"/> Single Hung <input checked="" type="checkbox"/> Double Hung <input type="checkbox"/> Single Pane <input checked="" type="checkbox"/> Dual Paned <input type="checkbox"/> Fixed <input type="checkbox"/> Casement <input type="checkbox"/> Metal <input checked="" type="checkbox"/> Wood <input type="checkbox"/> Vinyl Security Bars: <input type="checkbox"/> Present <input checked="" type="checkbox"/> Not Present <input type="checkbox"/> Safety Releases <input type="checkbox"/> Become familiar with operation of safety releases on security bars
Remarks	I Image of room. (See Figure #61) (See Figure #62)

Figure Number 61



Image of room.

Figure Number 62



Image of room.

Living Room/Entry

Floor Coverings	<input type="checkbox"/> Tile <input type="checkbox"/> Sheetgoods <input checked="" type="checkbox"/> Wood <input type="checkbox"/> Wall to Wall Carpet <input checked="" type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> Not Fully Visible
Walls	<input type="checkbox"/> Plaster <input checked="" type="checkbox"/> Drywall <input type="checkbox"/> Masonry <input type="checkbox"/> Common Cracks <input checked="" type="checkbox"/> Satisfactory
Ceilings	<input type="checkbox"/> Plaster <input checked="" type="checkbox"/> Drywall <input type="checkbox"/> Wood <input type="checkbox"/> Acoustical Tile <input type="checkbox"/> Common Cracks <input checked="" type="checkbox"/> Satisfactory
Stairs/Railings	<input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> N/A
Interior Doors	<input checked="" type="checkbox"/> Hollow Core <input type="checkbox"/> Raised Panel <input type="checkbox"/> Solid Core <input type="checkbox"/> ByPass <input type="checkbox"/> BiFold <input type="checkbox"/> Pocket <input type="checkbox"/> See Remarks
Windows	<input type="checkbox"/> Sliding <input type="checkbox"/> Single Hung <input checked="" type="checkbox"/> Double Hung <input checked="" type="checkbox"/> Single Pane <input type="checkbox"/> Dual Paned <input checked="" type="checkbox"/> Fixed <input type="checkbox"/> Casement <input type="checkbox"/> Metal <input checked="" type="checkbox"/> Wood <input type="checkbox"/> Vinyl Security Bars: <input type="checkbox"/> Present <input checked="" type="checkbox"/> Not Present <input type="checkbox"/> Safety Releases <input type="checkbox"/> Become familiar with operation of safety releases on security bars
Remarks	I Image of room. (See Figure #63) (See Figure #64) (See Figure #65)

Figure Number 63




Image of room.

Figure Number 64




Image of room.

Figure Number 65




Image of room.

Interior (Copy)

Floor Coverings	<input type="checkbox"/> Tile <input type="checkbox"/> Sheetgoods <input checked="" type="checkbox"/> Wood <input type="checkbox"/> Wall to Wall Carpet <input checked="" type="checkbox"/> Satisfactory <input checked="" type="checkbox"/> Not Fully Visible
Walls	<input type="checkbox"/> Plaster <input checked="" type="checkbox"/> Drywall <input type="checkbox"/> Masonry <input type="checkbox"/> Common Cracks <input checked="" type="checkbox"/> Satisfactory
Ceilings	<input type="checkbox"/> Plaster <input checked="" type="checkbox"/> Drywall <input type="checkbox"/> Wood <input type="checkbox"/> Acoustical Tile <input type="checkbox"/> Common Cracks <input checked="" type="checkbox"/> Satisfactory
Interior Doors	<input checked="" type="checkbox"/> Hollow Core <input type="checkbox"/> Raised Panel <input type="checkbox"/> Solid Core <input type="checkbox"/> Bypass <input type="checkbox"/> BiFold <input type="checkbox"/> Pocket <input type="checkbox"/> See Remarks
Windows/Doors	<input checked="" type="checkbox"/> Sliding <input type="checkbox"/> Single Hung <input type="checkbox"/> Double Hung <input type="checkbox"/> Single Pane <input checked="" type="checkbox"/> Dual Paned <input type="checkbox"/> Fixed <input type="checkbox"/> Casement <input type="checkbox"/> Metal <input checked="" type="checkbox"/> Wood <input type="checkbox"/> Vinyl Security Bars: <input type="checkbox"/> Present <input checked="" type="checkbox"/> Not Present <input type="checkbox"/> Safety Releases <input type="checkbox"/> Become familiar with operation of safety releases on security bars
Remarks	I Image of room. (See Figure #66) (See Figure #67)

Figure Number 66




Image of room.

Figure Number 67



Image of room.

Attic

Attic Access	<input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> N/A How Observed: From Service Platform <input type="checkbox"/> Not Observed <input type="checkbox"/> Scuttle Hole <input type="checkbox"/> Pull Down <input checked="" type="checkbox"/> Door <input type="checkbox"/> No Access Scuttle Hole Location: N/A <input checked="" type="checkbox"/> Inspection limited to view from access. Not all areas were completely visible.
Attic Access Location(s)	<input type="checkbox"/> Garage <input checked="" type="checkbox"/> Master Closet <input type="checkbox"/> Pantry <input type="checkbox"/> Laundry Room <input type="checkbox"/> Hallway
Moisture	<input type="checkbox"/> Some Signs <input type="checkbox"/> Extensive <input checked="" type="checkbox"/> None Observed <input type="checkbox"/> Condensation
Storage	<input checked="" type="checkbox"/> Heavy <input type="checkbox"/> Light <input type="checkbox"/> Floored <input type="checkbox"/> Not Floored
Insulation	<input type="checkbox"/> None <input checked="" type="checkbox"/> Batts <input type="checkbox"/> Fill <input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> N/A Installed in: <input type="checkbox"/> Rafters <input type="checkbox"/> Floor Approximate R Rating: 11 Approximate Inches: 3-4
Ventilation	<input type="checkbox"/> Window(s) <input type="checkbox"/> Attic Fan <input type="checkbox"/> Whole House Fan <input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> N/A <input type="checkbox"/> Ridge Vent <input type="checkbox"/> Soffit Vent <input type="checkbox"/> Turbine <input type="checkbox"/> Gable End Louvers <input checked="" type="checkbox"/> Roof Vents
Framing	<input type="checkbox"/> Cracked/Broken/Sagging Rafters <input checked="" type="checkbox"/> Satisfactory
Bracing	<input type="checkbox"/> Cracked/Broken/Sagging Bracing <input checked="" type="checkbox"/> Satisfactory
Remarks	<ul style="list-style-type: none"> I Ceiling light needs a cage around fixture. (See Figure #68) I Image of attic space. (See Figure #69) (See Figure #70)

Figure Number 68



Ceiling light needs a cage around fixture.

Figure Number 69



Image of attic space.

Figure Number 70




Image of attic space.

Structural

Type of Building	<input checked="" type="checkbox"/> Single Family <input type="checkbox"/> Duplex/Patio Home <input type="checkbox"/> Townhouse <input type="checkbox"/> Condominium <input checked="" type="checkbox"/> Wood Frame <input type="checkbox"/> Masonry Frame <input type="checkbox"/> Metal Frame <input checked="" type="checkbox"/> Gable Roof <input type="checkbox"/> Mansard Roof <input type="checkbox"/> Hip Roof <input type="checkbox"/> Flat Roof
Structure	Foundation: <input type="checkbox"/> Poured Concrete Slab <input type="checkbox"/> Sub Floor <input checked="" type="checkbox"/> Block Post Columns: <input type="checkbox"/> Steel <input type="checkbox"/> Masonry <input checked="" type="checkbox"/> Wood <input type="checkbox"/> Concrete <input type="checkbox"/> None <input type="checkbox"/> Not Visible Floor Structure: 2x10 Floor Joist & Masonry Footing Wall Structure: Wood Frame Roof Structure: Asphalt Shingles <input type="checkbox"/> Prefabricated Trusses
Remarks	I The west foundation wall has evidence of minor inward bowing. This appears to have been caused from the earth applying hydrostatic pressure against the foundation subsequently causing it to move. At this point movement appears to be older and cracks have been filled and painted. Recommend monitoring for further movement, if cracking or movement persists contact a qualified building contractor for repairs. (See Figure #71) (See Figure #72)

Figure Number 71



The west foundation wall has evidence of minor inward bowing. This appears to have been caused from the earth applying hydrostatic pressure against the foundation subsequently causing it to move. At this point movement appears to be older and cracks have been filled and painted. Recommend monitoring for further movement, if cracking or movement persists contact a qualified building contractor for repairs.

Figure Number 72



The west foundation wall has evidence of minor inward bowing. This appears to have been caused from the earth applying hydrostatic pressure against the foundation subsequently causing it to move. At this point movement appears to be older and cracks have been filled and painted. Recommend monitoring for further movement, if cracking or movement persists contact a qualified building contractor for repairs.

Basement / Crawlspace

Basement	<input checked="" type="checkbox"/> Full <input type="checkbox"/> Partial <input type="checkbox"/> None <input type="checkbox"/> Slab on Grade <input type="checkbox"/> N/A Walls: <input type="checkbox"/> Finished <input checked="" type="checkbox"/> Partitioned Ceiling: Drywall <input checked="" type="checkbox"/> Limited visibility due to basement storage
Floor	<input checked="" type="checkbox"/> Concrete <input type="checkbox"/> Carpeting <input type="checkbox"/> Sheetgoods <input checked="" type="checkbox"/> Satisfactory
Floor Drain	<input checked="" type="checkbox"/> Tested <input type="checkbox"/> Not Tested <input checked="" type="checkbox"/> Satisfactory <input type="checkbox"/> N/A
Crawl Space	<input checked="" type="checkbox"/> N/A <input type="checkbox"/> Wood to earth contact How Observed: Floor: <input type="checkbox"/> Concrete <input type="checkbox"/> Dirt Dampness: <input type="checkbox"/> Some Signs <input type="checkbox"/> Extensive <input type="checkbox"/> None Observed <input type="checkbox"/> Vapor Barrier <input type="checkbox"/> Insulation <input type="checkbox"/> Ventilation
Remarks	<ul style="list-style-type: none"> Image of basement. (See Figure #73) (See Figure #74) (See Figure #75) (See Figure #76) BASEMENT- Stairwell lacks a hand/guard rail. (See Figure #77) See Summary Remarks

Figure Number 73



Image of basement.

Figure Number 74




Image of basement.

Figure Number 75



Image of basement.

Figure Number 76



Image of basement.

Figure Number 77



BASEMENT- Stairwell lacks a hand/guard rail.